



SERVICE PRICING FOR AUTOSPORT PRODUCTS ÖHLINS NORTHERN EUROPE

Version 1.0, valid from 1.10.17

EXPLANATION

At Öhlins Northern Europe suspension is serviced to the manufacture's desired quality level.

The service charge includes only the labor time. At a regular service the product will be disassembled, all parts and components are checked for wear and all relevant seals will be replaced and charged seperately. After this the product will be assembled and filled with fresh oil through a vaccum filling machine.

Not included in the service charge are all damaged or worn parts apart from the standard service procedure. Additional cost may occur for replacing these.

Please note:

- Product sent for service have to be clean, otherwise 380 SEK will be charged for cleaning them.

By choosing Öhlins Northern Europe to service your products we guarantee the absolute highest level of quality and reliability.

Your workshop team at Öhlins Northern Europe.





SERVICE PRICING ÖHLINS NORTHERN EUROPE

These are the prices for servicing Autosport products at Öhlins Northern Europe. All prices are in SEK and per damper.

| Damper type | Service pricing, excl. VAT |
|--|----------------------------|
| Single damper (STX, 1, 2 or 3-way, DFV) | 1 235 SEK |
| Mac Pherson with Öhlins produced strut | 2 090 SEK |
| TPX, TTX -dampers | Offered case by case |
| Cleaning | 380 SEK |
| Dyno | 475 SEK |

All costs for seals etc will be charged separately.

